COMPLETION REPORT

1. Name of Work : **WARD MAINTENANCE OF WARD USING TRACTOR & LABOURS IN WARD NO.13 IN SSD (2.00 PM TO 10.00 PM)**

2. Sanctioned Estimate No. & Dt : JC/DZ/AA/243/13-14, Date: 30/10/2013, EE/DD/TS/2180/13-14, Date: 30/10/2013.

3. Head of Account which is Chargeable : PCode P-1771

4. Work Order No. & Dt : EE/DD/WO/174/13-14, Date: 20/12/2013,

5. Name of Contractor : **SRI R. SHIVARAM**

6a. Time stipulated for completion of work :

b. Delay in execution of work : --

7. Measurement recorded in : M.B. No. 1688

8. Check measurement of the Asst. : M.B. No. 1688 Page No. 168749/2

Asst. Exe. Eng. / Exe. Eng : Page No. 168749/2

9. Name of the Office / Official :

incharge of the work :

10. a) Asst. Engineer : Nagbushan.

b) Asst. Exe. Engineer : Ramachandra murthy.

Sanctioned estimated amount	Amount claims as per actually vide as per bills	DIFFERENCE	
		Excess	Savings
1200000/-	1130595/-	-	69405/-

1) Certified that the above work has been completed within the stipulated time noted in the work order.
2) Certified that the contractor has delayed and completed the work for which necessary fine has been recovered.
3) Certified that the above work has been executed by the contractor satisfactorily in accordance with the specification as embodied in the agreement.

ASST. ENGINEER

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶಬ್ಬಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

ASST. EXECUTIVE ENGINEER
SUB DIVISION
BRUHATH BANGALORE MAHANAGARA PALIKE

ಕಾರ್ಯಪಾಲಕರ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು-57.

30/5/14

ACCOUNTS SUPTD. ( )

ಮುಖ್ಯ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು.